




1/17



2/17



3/17



4/17




FIG. 5A





FIG. 5B






FIG. 7A





FIG. 7B



8/17




FIG. 9




FIG. 10




FIG. 11






FIG. 12



13/17



# REPLACEMENT SHEET

# 14/17

# FIG. 14

MANUFACTURER	BRAND	BASIS WEIGHT	TEMPERATURE	HUMIDITY	BIAS ROLL	AIR BLOWER	TRANSFER VOLTAGE
AAAAA	aaaaa	90gsm	~ 10°C	~ 40%	115 PULSE	ON	y = x + a1
				40 ~ 65%	115 PULSE	ON	y = x
			-	65 ~ 70%	70 PULSE	ON	y = x + a2
				70% ~	65 PULSE	ON	y = x + a2
			10 ~ 18°C	~ 40%	70 PULSE	ON	y = x + a1
				40 ~ 65%	60 PULSE	ON	y = x + a1
				65 ~ 70%	60 PULSE	ON	y = x
				70% ~	55 PULSE	ON	y = x
			18 ~ 25°C	~ 40%	70 PULSE	ON	y = x + a1
				40 ~ 65%	60 PULSE	ON	y = x + a1
				65 ~ 70%	60 PULSE	ON	y = x
			•	70% ~	55 PULSE	ON	y = x
			25°C ~	~ 40%	70 PULSE	ON	y = x
				40 ~ 65%	60 PULSE	ON	y = x
				65 ~ 70%	60 PULSE	ON	y = x
				70% ~	55 PULSE	ON	y = x
88888	bbbbb	82gsm	~ 10°C	~ 40%	130 PULSE	OFF	y = x + a1
				40 ~ 65%	110 PULSE	OFF	y = x + a3
				65 ~ 70%	60 PULSE	OFF	y = x + a3
				70%	60 PULSE	OFF	y = x + a3
			10 ~ 18°C	- 40%	85 PULSE	OFF	y = x + a1
	ł		[	40 ~ 65%	70 PULSE	OFF	y = x + a1
				65 ~ 70%	70 PULSE	OFF	y = x + a3
		Ĺ		70% ~	65 PULSE	OFF	y = x + a3
			18 ~ 25°C	- 40%	85 PULSE	OFF	y = x + a1
		1		40 ~ 65%	70 PULSE	OFF	y = x + a1
		į		65 ~ 70%	70 PULSE	OFF	y = x + a3
				70% ~	65 PULSE	OFF	y = x + a3
	-	Γ	25°C ~	~ 40%	75 PULSE	OFF	y = x + a4
				40 ~ 65%	70 PULSE	OFF	y = x + a4
			T T	65 ~ 70%	70 PULSE	OFF	y = x + a4
			F	70% ~	60 PULSE	OFF	y = x + a4

15/17

FIG. 15A




FIG. 15B






FIG. 15C



16/17



17/17

